




Here I am setting up the gear (milling attachment, tail stock and microscope) and aligning the first the microscope with the piece and then the cutter with the microscope. I set the cutting depth for the teeth.



While I am cutting the leaves.



While I am changing the division



After cutting the leaves I am parting it off.

